

# Oil Field Environmental Incident Summary

**Incident:** 20141011113656      **Date/Time of Notice:** 10/11/2014 11:36

**Responsible Party:** KODIAK OIL & GAS (USA) INC.

**Well Operator:** KODIAK OIL & GAS (USA) INC.

**Well Name:** WOOD 5-15H

**Field Name:** TRUAX

**Well File #:** 19857

**Date Incident:** 10/11/2014      **Time Incident:** 02:30

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 98

**Sec:** 15

**Qtr:**

**Location Description:**

**Submitted By:** Britiny Fabry

**Received By:**

**Contact Person:** David Faulkner  
1625 BROADWAY STE 250  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	35	Barrels	35	Barrels	35	barrels
Brine	40	Barrels	40	Barrels	40	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/26/2016

**Clean Up Concluded:** 10/12/2014

**Risk Evaluation:**

none

**Areal Extent:**

Wind carried some oil/water mist off of location into grass to the NW of location.

**Potential Environmental Impacts:**

Little bit of grass and soil contamination

**Action Taken or Planned:**

Contacted Strata corporation and Schiele Mobility to do the cleanup of the location. Schiele Mobility is vacing up the standing water and hauling it to an outside disposal facility. Strata is on their way to location and will start cleaning on and off location and hauling contaminated soil to an outside disposal facility. Soil will be tested as well. Inspection of all piping and valves is under go.

**Wastes Disposal Location:** An approved disposal site

**Agencies Involved:****Updates**

---

**Date:** 10/13/2014 **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to an on-location valve/piping leak, sprayed off location. Followup is necessary.

---

**Date:** 10/14/2014 **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 12:00; off site 12:20, light rain, north wind 15+ mph, 51 degrees. Photographs collected. Nicely constructed well facility with interior and exterior dikes and capture ditch on downgradient side. Active site with some cleanup vehicles and tankers present. Piles of soil from cleanup efforts still present on facility. Diking appears to have functioned correctly, capturing most of the release. Overspray area is to the north on steep upgradient slope. Area has been scraped to clean soil. Area is approximately 20 by 30 meters. No evidence of oil in scraped area or beyond into pasture. Needs followup to ensure replacement of topsoil and seeding.

---

**Date:** 4/28/2016    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 17:44, 4/28/2016.

Vegetation sparsely scattered on side hill, but there are no signs of remaining impacts.

No follow-up necessary.